



Roadside Inspection
August 1, 2012

RECEIVED
JUL 31 2012
IBEW LOCAL 266

Recently a SRP commercial motor vehicle was involved in a random roadside inspection conducted by DPS at Germaine/McQueen.

SRP was cited under:

- *393.60(d) Window tint on the left and right side is less 70% of light transmission*
- *392.82 (a)(1) Driving while using a hand held mobile device while driving a CMV*

The driver was not cited.

This is SRP's second violation in 2012 related to the use of a cell phone in a CMV while driving. The other violation occurred in February of 2012.

This is SRP's second violation in 2012 related to window tinting. The other violation occurred in February of 2012. Overall this is SRP's fourth violation for window tinting. The other violations occurred in 2008 and 2009.

Only the violations from 2012 will be associated with SRP's current CSA safety rating . The rating system includes violations from the past two years. Following this recent inspection, Transportation Services actively re-checked the window tinting on all of the affected commercial classified motor vehicles.

Both violations will remain on SRP's safety rating for two years and will be calculated into our safety rating for the *vehicle maintenance* and *unsafe driving* category.

If you have additional questions, please contact Randi Korte, extension 6-8124, or Fred Hauersperger, extension 6-5898.

Pam Cornelissens
IBW266